

Governor
Suzanne Dandoy, M.D., M.P.H.
Executive Director
Kenneth L. Alkema

DEPARTMENT OF HEALTH DIVISION OF ENVIRONMENTAL HEALTH

288 North 1460 West P.O. Box 16690 Salt Lake City, Utah 84116-0690 (801) 538-6121





DIVISION OF OIL, GAS & MINING

February 11, 1989

Mr. Joseph C. Milbourne North Lily Mining Company 851 Traeger St., Suite 320 San Bruno, CA 94066

Re: Tintic Project

Quality Assistance Testing

Dear Mr. Milbourne:

We have reviewed the construction quality assurance certification document for the Tintic project and have the following concerns:

- 1. The density values, for the secondary clay liner, which failed to meet the minimum requirement must have documentation of reworking and successful test results submitted for review.
- 2. The Matrecon, Inc. flexible membrane quality control test results must be evaluated for the following samples: P558-1, P588-8, P588-12 and P588-13 which did not meet the minimum requirements for bond seam strength. Your comments on this situation so we can evaluate the impacts on the integrity of the liner system and the project life must be submitted for review.
- 3. The Industrial and Environmental plastics Inc. flexible membrane quality control test must be evaluated for the following samples: LPFW-12, LPFW-16, LPFW-17, LPFW-19, LPFW-26, and LPFW-29 which did not meet the minimum requirements for bond seam strength. Your comments on this situation are requested so and evaluation of its impacts on the integrity of the liner system and the project life can be determined.

This information must be submitted to the Bureau within thirty (30) days of the receipt of this letter.

Please call Charlie Dietz if there are any questions.

Sincerely,

Kiran L. Bhayani, P.E., Manager

Design Evaluation Section

Bureau of Water Pollution Control

CDG/Ime

cc: Grant Pinkerton, North Lily Mining Lowell Braxton, Division of Oil, Gas & Mining Bruce Hall, Central Utah District Health Dept. 0943p48